



2019- 2020 Report  
CMR and IMR Projects

Acme School

# Roof Replacement

Replaced 2 Sections of Roof with SBS\*

Before

After



# Hallway Lights

Replaced Fluorescent Lights with LED Lights.



# New Breakout Room

Built a Breakout Room in Elementary Boot Room.

Before

After



# Flooring in Classrooms

Replaced Flooring in 3 Classrooms with New Rubber Tile Flooring.

Before

After



## Other Projects

1. Removed Dangerous Poplars and Broken Branches
2. Site Topography
3. Replaced 3 Toilets with Low Flow Toilets



2019- 2020 Report  
CMR and IMR Projects

École Brentwood  
Elementary

# HVAC

Replaced 8 Condenser Units and 5 Portable Furnaces

Before

After



# Windows

Replaced 11 Exterior Windows and Frames

Before

After



## Other Projects

1. Replaced Backflow Preventer on Boiler.
2. Replaced Motors on Entrance Heater
3. Installed Fire Door “Hold Opens”
4. Phase 2 Roof Replacement
5. Replaced Gym Lights with Dimmable LED Lights
6. Replacing Flooring in Hallway- To be completed Sept 25th
7. Touch up Painting



2019- 2020 Report  
CMR and IMR Projects

Carseland School


# Roof Replacement

Replaced Section of Roof with SBS\*

## Before



## After



# Kitchen

Repainted Cabinetry, Replaced Countertops, Installed Backsplash and 3 Compartment Sink

Before

After



**Carseland School**

# Office Flooring

Replaced Flooring in Reception, Infirmary, Staff Lounge with Vinyl Planking.

Before

Middle



After



# Replaced Gym Floor

Replaced Hardwood Floor with Rubber Gym Flooring

Before

After



## Other Projects

1. Replaced Pressure Release Valves on Boilers
2. Blinds Installed on Classroom Doors for Lock down
3. Indoor Air Quality Assessment
4. Replaced Washroom Flush Valves



2019- 2020 Report  
CMR and IMR Projects

Crowther Memorial Junior High

# Portable Classroom Lights

Replaced Fluorescent Lights with Dimmable LED Lights



# Hallway Upgrades

Replaced Fluorescent Lights and Ceiling Tile with LED Lights and New Acoustical Ceiling Grid and Tile.

During

After



# Wall Protection

Installed Wall Protection to help Prevent Vandalism in Portable Washroom



# Canteen Upgrades

Removed Curtain, Extended and Installed Fire Rated Wall

Before

After




# Flooring in Classrooms

Replaced Flooring in 3 Classrooms with New Rubber Tile Flooring.

## Before



## After



# Portable Hallway and Classroom

Replaced Flooring in 1 Classroom with Rubber Tile.

Before

After



# Skylights

Replaced Skylight Windows



# HVAC

Replaced 6 Roof Top Units and 40 ton Condenser

Before

After



**Crowther Memorial Junior High**

# Exterior Brick Wall

Removed Exterior Crumbling Brick Wall

Before

Middle

After



## Other Projects

1. Replaced Sanitary Sump Pumps in Portable Washroom
2. Installed CO Detectors
3. Replaced Back Flow Preventer on Boiler
4. Upgrade Building Management System
5. Painted Hallways



2019- 2020 Report  
CMR and IMR Projects

Dr. Elliott

# Drainage

Installed Hardscapes, Asphalt and Concrete Swale, for Drainage Issues.

Before

After



**Dr. Elliott School**

# Roof Replacement

Replaced 3 Sections of Roof with SBS\*

Before

After



# Flooring Replacement

Replaced Flooring in 3 Classrooms

Before

After



# Windows

Replacing 13 Windows and Frames – In Progress

Before

After



**Dr. Elliott School**

# Tree Removal

Removed Failing Poplar



## Other Projects

1. Replaced High School Hallway Lights with LED's and Added Electrical Surge Protection
2. Installed Sump Pump in Crawl Space
3. Replaced 3 Way Valves Actuators on Secondary Boiler Loop.
4. Installed Exterior Wall Damp Proofing
5. Installed Mechanical Venting in Crawl Space



2019- 2020 Report  
CMR and IMR Projects

Drumheller Valley  
Secondary School

# Fire Alarm Panel

Replaced Fire Alarm Panel and some Fire Alarm Device Upgrades



# Stair Treads & Risers

Replaced Main Stairwell Treads and Risers.

Before

After



# Windows

Replaced 6 Exterior Windows



**Drumheller Valley Secondary School**

# Other Projects

1. Replaced 1 Failed Flow Switch and 5 Expired Water Gauges on Fire Sprinkler System
2. Installed Hand Dryers in Locker Rooms



2019- 2020 Report

CMR and IMR Projects

Greentree Elementary School

# Classroom Remodeling

Replaced Drywall Ceiling with Acoustic Ceiling Tiles, Installed Dimmable LED Lights, Replaced Flooring in 3 Classrooms

Before

During

After



## Band Room

Replaced Bulletin Boards with Acoustic Tackable Wall Panels

Before

After



**Greentree School**

# Library Flooring

Installed Sump Pump and Replaced Flooring Due to Yearly Flooding

Before

After



During



Greentree School



# Gym Lights

Replaced Lights with Dimmable LED Lights



## Other Projects

1. Installed Chain Link Fence around Playground
2. Installed Emergency Lights in Student Washrooms and 2 Interior Classrooms for Safety
3. Replaced Elevator Cable and 2 Switches
4. Replacing 12 Windows – Still in Progress
5. Painted Part of Gym Wall, Classroom Doors and Frames



2019- 2020 Report  
CMR and IMR Projects  
Prairie Christian Academy

# Band Room

Installed Carpet Tile Over Hardwood Flooring.



## Other Projects

1. Installed Blinds Beside Classroom Doors for Lock downs
2. Installed Filters on Water Fountain



2019- 2020 Report  
CMR and IMR Projects  
Strathmore High School

# Floor Replacement

Replaced Flooring in 3 Classrooms

Before

After



# Gym Lights

Replaced Gym Lights with Dimmable LED Lights



# Hallway Lights

Replaced Hallway Sconce with LED Lights from Administration Office to Home Ec. Room.

Before

After



## Other Projects

1. Installed Backboard Stiffeners and Replaced 1 Winch and Cable.
2. Replaced Domestic and Irrigation Backflow Preventers
3. Replaced Boiler Relief Valve, Actuators and Zone Valves.
4. Removed Old Boiler
5. Upgraded PA System from Telecenter 21 to Telecenter U System
6. Replaced Main Control Board and Line Volt Stat on Air Handler
7. Installed AC/Ductless Split in Server Room to Reduce Heat.
8. Replaced 2 Compressors on Roof Top Unit #2 (Gym, Theatre)
9. Replaced Flooring in Barrier Free Washroom
10. Relocated 4 Fire Sprinkler Heads in Library Storage to Meet Code.



2019- 2020 Report  
CMR and IMR Projects


Three Hills School

# Exterior Drainage

Excavate and Reshape to Help with Drainage

Before

After




# Flooring

Replaced Flooring in 3 Classrooms

Before

After




# Gym Floor

Refinished Gym Floor

Before

After



# Roof Shingles

Replaced Shingles with SBS Shingles\*

Before



After



## Other Projects

1. Replaced Gas Valve, Low Water Cutoff Switch, Pneumatic Thermostats and Ignitor Pressure Switch on Boilers.
2. Replaced Gym Lights with Dimmable LED.
3. Replaced Sink with Stainless Steel Sink and Faucet
4. Replaced Flooring in Janitor Rom
5. Replaced 1 Roof Top Unit
6. Replaced some Washroom Lock Sets



2019- 2020 Report  
CMR and IMR Projects

Trinity Christian Academy

# Windows

Replaced 20 Windows and Frames

Before

After




# Flooring in Classroom

Replaced Flooring in 2 Classrooms with New Rubber Tile.

Before

After



# HVAC

Replaced 2 Portable Furnaces and Installed 2 New Condensers

Before

After



## New Condensers



# Other Projects

1. Replaced and Rewired Failed Flow Switch for Fire Sprinkler System.
2. Tied in Building Management System Critical Alarms into Security System.
3. Partial Roof Replacement
4. Washroom Reno Assessment
5. Installed 2 Hallway LED Lights



2019- 2020 Report  
CMR and IMR Projects


Westmount School

# Roof Replacement

Replaced 2 Sections of the Roof with SBS\*

Before

After



# Flooring

Replaced Flooring in Administration, Board Room, Staff Lounge, Vestibule and 3 Classrooms



## Other Projects

1. Replaced 7 Roof Top Units
2. Replaced Broken Sanitary Line Under Staff Parking Lot
3. Installed Heat Detectors in Storage Rooms Off Library
4. Replaced Furnace Duct Smoke Detector.
5. As per Code Requirement, Replaced Anit-Creep Device and Emergency Light on Lift Elevator.
6. Replaced Portable Furnace



2019- 2020 Report  
CMR and IMR Projects  
Wheatland Elementary

# Parking Lot

Remove Catch Basins due to Undermining of Parking Lot, Grade and Repair Asphalt

## Before



## After



# Lighting Upgrades - Administration

Replaced Light Fixtures with Dimmable LED Lights

Before

After



# Lighting Upgrades - Classrooms

Replaced Fluorescent Lights with Dimmable LED Lights in Multiple Classrooms



# Classroom Remodeling Sensory Room

Enclosed the Electrical Panel, Heating Pipes and Installed FRP  
Around the Walls.

Before

After



# Flooring - Classrooms

Replaced Flooring in 2 Classrooms with Rubber Tile



## Other Projects

1. Replaced 5 Portable Roof Top Units
2. Replaced Boiler Glycol Pump and Refractories
3. Replaced Glycol Expansion Tank
4. Touch Up Painting