



Maintenance Projects Review

2022-2023

Before



After



**Brentwood
Boiler Replacement**

CMJHS Bathroom Renovation





CMJHS Floor Replacement
Before



CMJHS Floor Replacement
After



Carbon School Light Upgrade


Carbon School Sinkhole



Exposed



Filled



Division Office Roof
Before



Division Office Roof
After



Dr Elliott Electrical -Before-



Progress





Completion




Before



After

DVSS Lighting Upgrades



DVSS Gym Floor Refinish



Learning Academy Renovation and Sewer Line Replacement



Before



During the Project



Completed

PCA Parking Lot Expansion








Completed

SHS Gym Floor Refinished



Before



After

SHS Breakout Room





Three Hills Hallway LED Upgrade

TCA Parking Lot Upgrade





During Reconstruction



Completed

TCA Sidewalk



TCA Locker Room Before



TCA Locker Room After





Trochu Bus Shop MUA

→



Install





Completed



Trochu Sidewalk



Before



After



Wheatland Crossing
Breakout Room
Before




During



Completed



Wheatland Crossing Fitness Room






As of Early October



Wheatland Crossing Modulars





During

Completed





Wheatland Elementary Lighting Upgrades



Before



After

Wheatland Elementary Amphitheatre

Acme School	Furnace Replacement	Dr. Elliott	Security System Upgrade	SHS	LED Lighting Upgrades
Brentwood School	PA System Upgrade	Dr. Elliott	BMS System Upgrade	SHS	Flush Valve Replacement
Brentwood School	Air Quality Testing	Dr. Elliott	Parking Lot Light Upgrade	SHS	Basketball Winch Replacement
Brentwood School	Security System Upgrade	Dr. Elliott	Electrical Distribution Upgrades	Storefront	Security System Upgrade
Carbon School	Security System Upgrade	Dr. Elliott	Boiler Replacement	Three Hills	Security System Upgrade
Carseland School	Security System Upgrade	Greentree	Fire Sprinkler & Alarm Replacements	Three Hills	Backstop Winch Replacement
Carseland School	Carpet Replacement	Greentree	LED Lighting Upgrade (stairwells & entrances)	Three Hills	Roof Top Unit Upgrades
CMJHS	Washroom Renovation	Greentree	Washroom Renovation	TCA	PA System Upgrades
CMJHS	Security System Upgrade	Greentree	Security System Upgrade	TCA	Security System Upgrade
CMJHS	Fire Alarm Upgrades	Greentree	Window Replacement	TCA	Electrical Ground Fault Replacement
CMJHS	Carpet Replacement	Greentree	Boiler Upgrades	TCA	BMS System Upgrade
CMJHS	T-Bar Replacement	PCA	Security System Upgrade	TCA	Lighting Upgrade
CMJHS	Boiler Replacement	PCA	Roof Replacement	TCA	Gym Change Rooms
DVSS	Gym Floor Refinish	SHS	Gym Floor Refinish	Trochu	Security System Upgrade
DVSS	Security System Upgrade	SHS	Security System Upgrade	Trochu	Install Dividing Wall
DVSS	Lighting Upgrades	SHS	Build Breakout Room	Trochu	Sidewalk Replacement

Trochu	Exterior Security Camera Installation	Wheatland Crossing	Waste Treatment Plant Installation
Westmount	Security System Upgrade	Wheatland Crossing	BMS Temperature Sensors
Westmount	Sidewalk Replacement	Wheatland Crossing	Window Replacement
Westmount	RTU Motor Replacement	Wheatland Crossing	PA System Replacement
Westmount	Security Camera Installation	Wheatland Crossing	Fire Pump Module Replacement
Westmount	Window Replacement	Wheatland Crossing	Structural Inspection
Wheatland Elm	PA System Upgrade	Wheatland Crossing	Security Camera Installation
Wheatland Elm	Security Camera Installation	Wheatland Crossing	Window Replacement
Wheatland Elm	VFD's on AHU Installation	DVSS Dorm	Hot Water Tank Replacement
Wheatland Elm	Partial Roof Replacement	DVSS Dorm	Lighting Upgrades
Wheatland Elm	Carpet Replacement (Stairs)	Trinity Dorm	Lighting Upgrades
Wheatland Elm	Gym Light Upgrades	Trinity Dorm	Window & Window Frame Replacement